

FIG. 1





FIG. 2



400





FIG. 4

FIG. 5



600





FIG. 6

FIG. 7






FIG. 8



910

Parameter Identifier	PDL	Web	J1939	RS-422	Universal Storage (US)
PID 1 (rpm)	x1	x1/2	x10	x100	200
PID 2 (temperature)	Scale	Scale	Scale	Scale	Value
PID R-1					
PID R	Scale	Scale	Scale	Scale	Value

FIG. 9




FIG. 10

1100




FIG. 11